

GDDS	GDKM	OBNO	RGNO	GDRE
Rev 20.000	19820	55491	B64KHV	20151027
rev 40000 km	38200	55491	B64KHV	20160331
Inspectie service 60000 KM	60513	55491	B64KHV	20170111
Intretinere service ** Munca suplimentara	60513	55491	B64KHV	20170111
Ulei de motor - 05W30 EM - Nou	60513	55491	B64KHV	20170111
Filtru de ulei - - - AUGSBURG	60513	55491	B64KHV	20170111
Filtru de aer - - - AUGSBURG	60513	55491	B64KHV	20170111
Filtru de combustibil - - - AUGSBURG	60513	55491	B64KHV	20170111
Filtru de polen - - - AUGSBURG	60513	55491	B64KHV	20170111
Ecotaxa ulei	60513	55491	B64KHV	20170111
Reparatie ITP	65356	55491	B64KHV	20170306
Inlocuiti Placute frana fata	74544	55491	B64KHV	20170523
Demontare si montare Manopera mecanica	74544	55491	B64KHV	20170523
Placute frana fata - MOTORCRAFT - Nou	74544	55491	B64KHV	20170523
Inlocuiti Filtru de aer	81321	55491	B64KHV	20170703
Inspectie service 80000 KM	81321	55491	B64KHV	20170703
Intretinere service ** Munca suplimentara	81321	55491	B64KHV	20170703
Filtru de aer - - - AUGSBURG	81321	55491	B64KHV	20170703
Ulei de motor - 05W30 EM - Nou	81321	55491	B64KHV	20170703
Filtru de ulei - - - AUGSBURG	81321	55491	B64KHV	20170703
Filtru de polen - - - AUGSBURG	81321	55491	B64KHV	20170703
Ecotaxa ulei	81321	55491	B64KHV	20170703
Janta roata fata stanga	81420	55491	B64KHV	20170712
Janta roata fata dreapta	81420	55491	B64KHV	20170712
Inlocuiti Lampa pozitie frana spate stanga	86684	55491	B64KHV	20170904
Lampa pozitie frana spate stanga	86684	55491	B64KHV	20170904
Reglaj faruri	92481	55491	B64KHV	20170929

Inlocuiti Bec far stanga	92481	55491	B64KHV	20170929
Bec far stanga	92481	55491	B64KHV	20170929
Reglaj faruri	96115	55491	B64KHV	20171020
Inlocuiti Bec far dreapta	96115	55491	B64KHV	20171020
Bec far dreapta	96115	55491	B64KHV	20171020
Inlocuiti Filtru de aer	100099	55491	B64KHV	20171114
Inspectie service 100000 KM	100099	55491	B64KHV	20171114
Intretinere service ** Munca suplimentara	100099	55491	B64KHV	20171114
Filtru de aer - - - AUGSBURG	100099	55491	B64KHV	20171114
Ulei de motor - 05W30 EM	100099	55491	B64KHV	20171114
Filtru de ulei - - - AUGSBURG	100099	55491	B64KHV	20171114
Filtru de polen - - - AUGSBURG	100099	55491	B64KHV	20171114
Ecotaxa ulei	100099	55491	B64KHV	20171114
Janta roata fata stanga	104785	55491	B64KHV	20171220
Inlocuiti Disc frana fata stanga / Inlocuiti Disc frana fata dreapta	106303	55491	B64KHV	20180129
Disc frana fata stanga - - - AUGSBURG	106303	55491	B64KHV	20180129
Disc frana fata dreapta - - - AUGSBURG	106303	55491	B64KHV	20180129
Placute frana fata - MOTORCRAFT - Economic	106303	55491	B64KHV	20180129
Inlocuiti Baterie	112848	55491	B64KHV	20180516
Baterie	112848	55491	B64KHV	20180516
Reglaj faruri	113632	55491	B64KHV	20180530
Inlocuiti Bec far dreapta	113632	55491	B64KHV	20180530
Bec far dreapta	113632	55491	B64KHV	20180530
Inspectie service 120000 KM	119355	55491	B64KHV	20180816
Intretinere service ** Munca suplimentara	119355	55491	B64KHV	20180816
Ulei de motor - 00W30 OEM	119355	55491	B64KHV	20180816
Filtru de ulei - KNECHT - AUGSBURG	119355	55491	B64KHV	20180816
Filtru de aer - BOSCH - AUGSBURG	119355	55491	B64KHV	20180816

29/11/2018

Istoric mentenanta B64KHV



Filtru de combustibil - - - AUGSBURG	119355	55491 B64KHV	20180816
Filtru de polen - KNECHT - AUGSBURG	119355	55491 B64KHV	20180816
Ecotaxa ulei	119355	55491 B64KHV	20180816

LeasePlan Romania SRL

Barbu Vacarescu 301-311, Cladirea Lakeview, Etaj 12, Sector 2, 020276, Bucuresti | T: +4021 407 2142 | F: +4021 407 2149