

GDDS	GDKM	OBNO	RGNO	GDRE
rev 20.000,complet antigel	19905	49179	B135COF	20141124
Inlocuiti Bec far stanga	39662	49179	B135COF	20150711
Inlocuiti Filtru de aer	39662	49179	B135COF	20150711
Inlocuiti Filtru de combustibil / Inlocuiti Filtru de combustibil	39662	49179	B135COF	20150711
Inlocuiti Filtru antipolen	39662	49179	B135COF	20150711
Inspectie service 40000 KM	39662	49179	B135COF	20150711
Inlocuiti Placute frana fata	39662	49179	B135COF	20150711
Inlocuiti Stergatoare parbriz	39662	49179	B135COF	20150711
WD 40	39662	49179	B135COF	20150711
Lama stanga stergator parbrize	39662	49179	B135COF	20150711
Lama dreapta stergator parbriz	39662	49179	B135COF	20150711
Bec far stanga	39662	49179	B135COF	20150711
Placute frana fata	39662	49179	B135COF	20150711
Filtru antipolen - DENSO - Nou	39662	49179	B135COF	20150711
Buson baie de ulei	39662	49179	B135COF	20150711
Filtru de ulei	39662	49179	B135COF	20150711
Filtru de aer	39662	49179	B135COF	20150711
Filtru de combustibil	39662	49179	B135COF	20150711
Ulei de motor - 05W30-ACEA-C3	39662	49179	B135COF	20150711
Ecotaxa ulei	39662	49179	B135COF	20150711
Inlocuiti Filtru de aer	59431	49179	B135COF	20151023
Inlocuiti Filtru de combustibil	59431	49179	B135COF	20151023
Inlocuiti Filtru de polen	59431	49179	B135COF	20151023
Inspectie service 60000 KM	59431	49179	B135COF	20151023
Demontare si montare Tambur frana spate stanga / Demontare si montare Tambur frana spate dreapt	59431	49179	B135COF	20151023
Inlocuiti Tambur frana spate stanga / Inlocuiti Tambur frana spate dreapta	59431	49179	B135COF	20151023
Ulei de motor - 05W30 ACEA - Nou	59431	49179	B135COF	20151023

Ecotaxa ulei	59431	49179	B135COF	20151023
Buson baie de ulei	59431	49179	B135COF	20151023
Filtru de ulei	59431	49179	B135COF	20151023
Filtru de combustibil	59431	49179	B135COF	20151023
Filtru de aer	59431	49179	B135COF	20151023
Filtru de polen - VALEO - Nou	59431	49179	B135COF	20151023
Inlocuiti Filtru de aer	79450	49179	B135COF	20160523
Inlocuiti Filtru de combustibil	79450	49179	B135COF	20160523
Inlocuiti Filtru de polen	79450	49179	B135COF	20160523
Inspectie service 80000 KM	79450	49179	B135COF	20160523
Inlocuiti Placute frana fata	79450	49179	B135COF	20160523
Inlocuiti Curea de distributie / Inlocuiti Set distributie / Inlocuiti Rulment intinzator curea distributie	79450	49179	B135COF	20160523
Reparatie ITP	79450	49179	B135COF	20160523
Ulei de motor - 05W30-ACEA-C3	79450	49179	B135COF	20160523
Ecotaxa ulei	79450	49179	B135COF	20160523
Buson baie de ulei	79450	49179	B135COF	20160523
Set distributie	79450	49179	B135COF	20160523
Kit curea de accesorii	79450	49179	B135COF	20160523
Filtru de ulei	79450	49179	B135COF	20160523
Filtru de combustibil	79450	49179	B135COF	20160523
Filtru de aer	79450	49179	B135COF	20160523
Filtru de polen - VALEO - Nou	79450	49179	B135COF	20160523
Placute frana fata	79450	49179	B135COF	20160523
Antigel	79450	49179	B135COF	20160523
Rulment curea accesorii	79450	49179	B135COF	20160523
Inlocuiti Filtru de aer	100006	49179	B135COF	20161019
Inlocuiti Filtru de combustibil	100006	49179	B135COF	20161019
Inlocuiti Filtru de polen	100006	49179	B135COF	20161019

Inspectie service 100000 KM	100006	49179	B135COF	20161019
Filtru de polen - VALEO - Nou	100006	49179	B135COF	20161019
Buson baie de ulei	100006	49179	B135COF	20161019
Filtru de ulei	100006	49179	B135COF	20161019
Filtru de aer	100006	49179	B135COF	20161019
Filtru de combustibil	100006	49179	B135COF	20161019
Ulei de motor - 05W30-ACEA-C3	100006	49179	B135COF	20161019
Ecotaxa ulei	100006	49179	B135COF	20161019
Inlocuiti Lampa pozitie fata dreapta	120246	49179	B135COF	20170706
Inlocuiti Filtru de aer	120246	49179	B135COF	20170706
Inlocuiti Filtru de combustibil	120246	49179	B135COF	20170706
Inlocuiti Filtru de polen	120246	49179	B135COF	20170706
Inlocuiti Lichid de frana	120246	49179	B135COF	20170706
Inspectie service 120000 KM	120246	49179	B135COF	20170706
Demontare si montare Tambur frana spate stanga / Demontare si montare Tambur frana spate dreapt	120246	49179	B135COF	20170706
Inlocuiti Tambur frana spate stanga / Inlocuiti Tambur frana spate dreapta	120246	49179	B135COF	20170706
Inlocuiti Placute frana fata	120246	49179	B135COF	20170706
Inlocuiti Antigel	120246	49179	B135COF	20170706
Lampa pozitie fata dreapta	120246	49179	B135COF	20170706
Placute frana fata	120246	49179	B135COF	20170706
Filtru de polen - VALEO - Nou	120246	49179	B135COF	20170706
Buson baie de ulei	120246	49179	B135COF	20170706
Filtru de ulei	120246	49179	B135COF	20170706
Filtru de aer	120246	49179	B135COF	20170706
Filtru de combustibil	120246	49179	B135COF	20170706
Ulei de motor - 05W30-ACEA-C3	120246	49179	B135COF	20170706
Antigel	120246	49179	B135COF	20170706
Lichid de frana	120246	49179	B135COF	20170706



Ecotaxa ulei	120246	49179	B135COF	20170706
Inlocuiti Filtru de aer	140360	49179	B135COF	20171214
Inlocuiti Filtru de combustibil	140360	49179	B135COF	20171214
Inlocuiti Filtru de polen	140360	49179	B135COF	20171214
Inspectie service 140000 KM	140360	49179	B135COF	20171214
Inlocuiti Stergatoare parbriz	140360	49179	B135COF	20171214
Lamela stanga stergator parbriz	140360	49179	B135COF	20171214
Lamela dreapta stergator parbriz	140360	49179	B135COF	20171214
Filtru de polen - VALEO - Nou	140360	49179	B135COF	20171214
Buson baie de ulei	140360	49179	B135COF	20171214
Filtru de ulei	140360	49179	B135COF	20171214
Filtru de aer	140360	49179	B135COF	20171214
Filtru de combustibil	140360	49179	B135COF	20171214
Ulei de motor - 05W30-ACEA-C3	140360	49179	B135COF	20171214
Ecotaxa ulei	140360	49179	B135COF	20171214
Reparatie ITP	149871	49179	B135COF	20180517