

GDDS	GDKM	OBNO	RGNO	GDRE
placute frana,	17601	55785	B65HZT	20151216
revizie 20000 km,	18694	55785	B65HZT	20151229
verificare inst AC	26740	55785	B65HZT	20160523
verificare frane, inl pl fr fata,poze	28783	55785	B65HZT	20160523
martor lichid racire aprins in bord aleator, carcasa termostat pierderi	35627	55785	B65HZT	20160810
Inlocuiti Disc frana fata stanga / Inlocuiti Disc frana fata dreapta	39870	55785	B65HZT	20161021
Inlocuiti Filtru de aer	39870	55785	B65HZT	20161021
Inspectie service 40000 KM	39870	55785	B65HZT	20161021
Intretinere service ** Munca suplimentara	39870	55785	B65HZT	20161021
Disc frana fata stanga - - - AUGSBURG	39870	55785	B65HZT	20161021
Disc frana fata dreapta - - - AUGSBURG	39870	55785	B65HZT	20161021
Placute frana fata - MOTORCRAFT - Nou	39870	55785	B65HZT	20161021
Filtru de aer - - - AUGSBURG	39870	55785	B65HZT	20161021
Ulei de motor - 05W30 EM - Nou	39870	55785	B65HZT	20161021
Filtru de ulei - - - AUGSBURG	39870	55785	B65HZT	20161021
Filtru de polen - - - AUGSBURG	39870	55785	B65HZT	20161021
Ecotaxa ulei	39870	55785	B65HZT	20161021
Reparatie ITP	54047	55785	B65HZT	20170404
Inlocuiti Placute frana fata	55073	55785	B65HZT	20170411
Demontare si montare Manopera mecanica	55073	55785	B65HZT	20170411
Placute frana fata - MOTORCRAFT - Nou	55073	55785	B65HZT	20170411
Inlocuiti Lampa pozitie frana spate stanga	57018	55785	B65HZT	20170511
Inlocuiti Lampa pozitie frana spate dreapta	57018	55785	B65HZT	20170511
Lampa pozitie frana spate stanga - - - AUGSBURG	57018	55785	B65HZT	20170511
Lampa pozitie frana spate dreapta - - - AUGSBURG	57018	55785	B65HZT	20170511
Inspectie service 60000 KM	59454	55785	B65HZT	20170613
Intretinere service ** Munca suplimentara	59454	55785	B65HZT	20170613

Filtru de combustibil	59454	55785 B65HZT	20170613
Ulei de motor - 05W30 EM - Nou	59454	55785 B65HZT	20170613
Filtru de ulei - - - AUGSBURG	59454	55785 B65HZT	20170613
Filtru de aer - - - AUGSBURG	59454	55785 B65HZT	20170613
Filtru de polen - - - AUGSBURG	59454	55785 B65HZT	20170613
Ecotaxa ulei	59454	55785 B65HZT	20170613
Inlocuiti Placute frana fata	77087	55785 B65HZT	20180201
Demontare si montare Manopera mecanica	77087	55785 B65HZT	20180201
Placute frana fata - MOTORCRAFT - Economic	77087	55785 B65HZT	20180201
Inlocuiti Filtru de aer	78900	55785 B65HZT	20180301
Inspectie service 80000 KM	78900	55785 B65HZT	20180301
Intretinere service ** Munca suplimentara	78900	55785 B65HZT	20180301
Filtru de aer - KNECHT - AUGSBURG	78900	55785 B65HZT	20180301
Ulei de motor - 05W30 EM	78900	55785 B65HZT	20180301
Filtru de ulei - KNECHT - AUGSBURG	78900	55785 B65HZT	20180301
Filtru de polen - KNECHT - AUGSBURG	78900	55785 B65HZT	20180301
Ecotaxa ulei	78900	55785 B65HZT	20180301
Inlocuiti Placute frana fata	91660	55785 B65HZT	20180917
Reparatie Verificare stand franare	91660	55785 B65HZT	20180917
Placute frana fata - MOTORCRAFT - Economic	91660	55785 B65HZT	20180917
Inlocuiti Baterie	92541	55785 B65HZT	20181019
Verificati Baterie	92541	55785 B65HZT	20181019
Baterie	92541	55785 B65HZT	20181019