

GDDS	GDKM	OBNO	RGNO	GDRE
Revizie 20.000 km - ulei+filtru ulei;	20381	62010	B190DOR	20160428
Inl. set placute frana fata;	24053	62010	B190DOR	20160530
rev 40000 km, inl pl fr spate	39863	62010	B190DOR	20161111
zgomot la viraje, inl tg bieleta directie stg,inl tg port USB,inl pl fr fata,baterie telec/verdo/ se comanda	44748	62010	B190DOR	20170203
Revizie: ulei, filtru ulei, filtru aer, lichid frana;	61070	62010	B190DOR	20170620
Inlocuiti Disc frana fata stanga / Inlocuiti Disc frana fata dreapta	65699	62010	B190DOR	20170810
Inlocuiti Placute frana fata	65699	62010	B190DOR	20170810
Disc frana fata stanga	65699	62010	B190DOR	20170810
Disc frana fata dreapta	65699	62010	B190DOR	20170810
Placute frana fata	65699	62010	B190DOR	20170810
itp	73385	62010	B190DOR	20171004
Inspectie service 80000 KM	80959	62010	B190DOR	20171121
Verificati bujiile	80959	62010	B190DOR	20171121
Inlocuiti Filtru de combustibil	80959	62010	B190DOR	20171121
Inlocuiti Cureau de accesorii	80959	62010	B190DOR	20171121
Reparatie Telecomanda inchidere centralizata	80959	62010	B190DOR	20171121
Inlocuiti Placute frana spate	80959	62010	B190DOR	20171121
Spray	80959	62010	B190DOR	20171121
Cureau de accesorii	80959	62010	B190DOR	20171121
Placute frana spate	80959	62010	B190DOR	20171121
Filtru de combustibil	80959	62010	B190DOR	20171121
Filtru de polen	80959	62010	B190DOR	20171121
Filtru de ulei	80959	62010	B190DOR	20171121
Ulei de motor - 05W30 ACEA	80959	62010	B190DOR	20171121
Ecotaxa ulei	80959	62010	B190DOR	20171121