

Maintenance and Repair Report

FORD FIESTA (B81BCE)

Kilometraj	Descriere	Întreținută și reparată de	Data
157 534 Km	ITP		09/02/2021
155 356 Km	Antigel		28/01/2021
155 356 Km	Kit accesorii		28/01/2021
155 356 Km	Kit distributie		28/01/2021
155 356 Km	Kit distributie + pompa apa, senzor debit aer		28/01/2021
155 356 Km	Pompa apa		28/01/2021
155 356 Km	Senzor debit aer		28/01/2021
150 143 Km	Bec far		16/11/2020
150 143 Km	Bielele ar fata		16/11/2020
150 143 Km	Cap bara dr. si stg.		16/11/2020
150 143 Km	Clema fixare suport capota		16/11/2020
150 143 Km	Comutator media volan		16/11/2020
150 143 Km	Rulment roata fata		16/11/2020
150 143 Km	Rulment roata fata dreapta, bielele antiruliu si capete bara		16/11/2020
146 521 Km	Filtru aer		30/09/2020
146 521 Km	Filtru praf si polen		30/09/2020
146 521 Km	Filtru ulei		30/09/2020
146 521 Km	Manopera revizie (KM)		30/09/2020
146 521 Km	Saiba buson golire		30/09/2020
146 521 Km	Ulei motor		30/09/2020
146 129 Km	Bec stop frana		24/09/2020
146 129 Km	Discuri frana fata		24/09/2020
146 129 Km	Inlocuit bec		24/09/2020
146 129 Km	Inlocuit discuri si placute fata		24/09/2020
146 129 Km	Placute frana fata		24/09/2020
146 129 Km	Receptie vehicul		24/09/2020
146 129 Km	Stand frane/suspensie		24/09/2020
134 660 Km	Lichid frana		24/04/2020
134 660 Km	Stand frane		24/04/2020
134 660 Km	Verificare sistem franare		24/04/2020
126 265 Km	Filtru aer		30/01/2020
126 265 Km	Filtru combustibil		30/01/2020
126 265 Km	Filtru praf si polen		30/01/2020
126 265 Km	Filtru ulei		30/01/2020
126 265 Km	Ulei motor		30/01/2020
0 Km	Manopera revizie (KM)		30/01/2020
105 668 Km	Bec far		26/09/2019
105 668 Km	Filtru aer		26/09/2019
105 668 Km	Filtru praf si polen		26/09/2019
105 668 Km	Filtru ulei		26/09/2019
105 668 Km	Inlocuit bec		26/09/2019
105 668 Km	Inlocuit filtru aer		26/09/2019
105 668 Km	Inlocuit filtru polen		26/09/2019
105 668 Km	Inlocuit placute frana fata		26/09/2019
105 668 Km	Inlocuit ulei motor		26/09/2019
105 668 Km	Manopera revizie 1an		26/09/2019
105 668 Km	Placute frana fata		26/09/2019
105 668 Km	Stand frane/suspensie		26/09/2019
105 668 Km	Ulei motor		26/09/2019
93 232 Km	Geometrie roti		21/06/2019
84 760 Km	Filtru aer		25/03/2019
84 760 Km	Filtru praf si polen		25/03/2019
84 760 Km	inl lichid de frana		25/03/2019
84 760 Km	Lichid frana		25/03/2019
84 760 Km	Manopera revizie (KM)		25/03/2019
84 760 Km	Revizie tip A(ulei,f.ulei)		25/03/2019
81 451 Km	ITP		15/02/2019
63 211 Km	Filtru aer		30/08/2018
63 211 Km	Filtru combustibil		30/08/2018
63 211 Km	Filtru praf si polen		30/08/2018
63 211 Km	inl pl frana		30/08/2018
63 211 Km	Manopera revizie (KM)		30/08/2018
63 211 Km	Placute frana fata		30/08/2018
0 Km	Revizie tip A(ulei,f.ulei)		30/08/2018
41 850 Km	Filtru praf si polen		28/02/2018
41 850 Km	Manopera revizie (KM)		28/02/2018
41 850 Km	Revizie tip A(ulei,f.ulei)		28/02/2018
20 780 Km	FILTRU AER		31/10/2017
20 780 Km	FILTRU POLEN		31/10/2017
20 780 Km	FILTRU ULEI		31/10/2017
20 780 Km	REVIZIE 584350		31/10/2017
20 780 Km	ULEI		31/10/2017